

Report no. LP-2025-0483 Date 14 May 2025 Language English

TYPE: SUPPLIER VISIT (UP TO 3 HRS ON SITE)

Supplier visit

Anonymised sample. Client data is redacted and photos are blurred to protect clients.

KEY DATA

Supplier	■■■■■■■■■■ Co., Ltd. — Guangdong
Visit / duration	13 May 2025 · 2 hrs 40 min
Location	Industrial park ■■■■■■■■■■, Dongguan
Inspector	Vinko Kolar

RESULT AT A GLANCE

- ✓ Factory exists at the stated address
- ✓ Production of the product group observed on site
- ! Company smaller than stated



— PHOTO DOCUMENTATION



Fig. 1 – Façade & company sign




Fig. 2 – Reception with logo



Fig. 3 – Production hall, line 2



Fig. 4 – Product from ongoing production



Fig. 5 – Packing & carton storage



Fig. 6 – Final check at line end

— OBSERVATIONS

- The address leads to a real production site, not an office.
- Two active production lines for the product group in operation.
- Visible workforce smaller than the stated ~80 people.

— COMPARISON WITH YOUR CHECKLIST

CRITERION	RESULT
Company at stated address	Confirmed
Own production (not intermediary)	Plausible
Product group in the range	Confirmed
Company size (~80 staff)	Deviation: ~50–60

— OVERALL ASSESSMENT

The supplier exists, produces the requested product group itself and makes a solid overall impression. The stated size is set too high — not a knock-out, but relevant for order volumes and deadlines. A sample order before the main order is recommended.

What this report is — and is not
This report documents a personal check to the best of my knowledge. It is not a certified QC inspection to standard, not legal advice and not a guarantee for future deliveries. It supports your own decision with traceable facts.